

September 8, 2018

Version 1

Safety Recall: 2017-18 NSX Fuel Tank Product Update: 2017 NSX Thermostat

AFFECTED VEHICLES

Year	Model	Trim	VIN Range
2017-18	NSX	ALL	Check the iN VIN status for eligibility.

BACKGROUND

The safety recall portion of this bulletin refers to the welds in the fuel tank for the crossover pipe that are improperly sealed. Clients may notice a strong fuel smell.

There is additionally a product update portion that refers to the thermostat inner seal that detaches and allows the thermostat to be held open. This causes the coolant temperature to increase higher than the expected rate which causes the MIL to come on with DTC P0128 (cooling system malfunction).

When this temporary placeholder bulletin appears during an iN VIN Status Inquiry, this vehicle is subject to a Safety Recall. This vehicle is on STOP SALE until further notice. Check for an iN message for further details. Refrain from calling Tech Line for updates.

This bulletin will be updated once Parts Information, Warranty Claim Information, and Repair Procedures are available.

END

CLIENT INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.