

[Next Unread Message](#)

[View Message](#)

Sent on	09	12	2018	Expires on	10	01	2018
From	Motorcycle National Field Service						
Subject	INTERIM SERVICE BULLETIN: 2018 CRF250L Wire Harness Inspection						

September 12, 2018

Re: INTERIM SERVICE BULLETIN: 2018 CRF250L Wire Harness Inspection

Dear Honda Dealer:

The interim Service Bulletin in support of the SAFETY RECALL for model year 2018 CRF250L motorcycles to inspect and, if necessary, replace the wire harness is posted on iN.

INTERIM SERVICE BULLETIN

[Service Bulletin CRF250L #1](#), includes the affected VIN information, inspection procedure, as well as warranty claim information.

The Repair Procedure for a damaged wire harness will be added to the bulletin in the near future.

Make sure all departments in your dealership are aware of this action.

If you have any questions, please contact AHM TechLine through TechLine Connect on *iN* or contact your District Service Manager.

Sincerely,

American Honda Motor Co., Inc.
Motorcycle Division

Bulletin #: 18-0279