



Highland
RIDGE RV



FORD CHASSIS RECALL - improper heat treatment of wheel studs

Jayco Recall 18V-689

Publication October 2018

Date:

Make: Jayco Motorized

Model: Precept

 Precept Prestige

Model Year: 2019

INCIDENT	Per Ford Recall 18V470 –Front wheel hub assemblies may contain wheel studs that were not heat treated properly. If a sufficient quantity of wheel studs breaks on one hub assembly, vehicle handling could be affected, increasing the risk of a crash. Ford Service Centers will inspect the front wheel hub assemblies and studs and replace affected studs if necessary. The recall remedy is free of charge and will take approximately one half-day.
AFFECTED UNITS	K1UA0085 K1UG0054,0055, 058 K1UK0101-0109, K1UL0166-0174 K1DT8080 8081

FORD MOTOR COMPANY IS ADMINISTERING THIS RECALL

If you have questions, please contact Motorhome Customer Assistance Center 1-866-906-9811