

Subarunet Announcement



**To: All Subaru Retailer Parts Departments
From: SOA Service & Quality Dept.**

Attention: Subaru Service and Parts Managers

**From: Subaru of America, Inc.
Date: November 21, 2018**

Subject: WTW-82 Repair Procedures for New In-Stock Unsold 2018 Legacy / Outback Units

Prior Subarunet messages for WTW-82 have addressed part ordering procedures and claim submission instructions for the repair of New In-Stock Unsold 2018 Legacy/ Outback models impacted by the WTW-82 Recall. Please refer to those Subarunet documents for the related information.

Techline has received several calls inquiring about repair procedures for the installation of combination meters supplied through United Radio as outlined in the earlier Subarunet messages. There are no special procedures for the installation of these combination meters.

Technicians are advised to follow the service procedures for combination meter replacement as outlined in the applicable Service Manual and the related Registration Manual for Immobilizer as found on STIS to complete these repairs.