

**Recall Quarterly Report****18V-850**

**Manufacturer Name :** Mercedes-Benz USA, LLC.  
**NHTSA Recall No. / MFR Recall No. :** 18V-850 /2019080012  
**Recall Subject :** Steering Rack Locknut May Fail, Affecting Steering  
**Owner Notification Beginning Date :** AUG 23, 2019  
**Owner Notification End Date:** DEC 30, 2019



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
5	OCT 16, 2020	2020-3	6,373	5,366	0	0
4	JUL 14, 2020	2020-2	6,373	5,034	0	0
3	APR 17, 2020	2020-1	6,373	4,513	0	0
2	JAN 13, 2020	2019-4	6,373	3,717	0	0
1	OCT 07, 2019	2019-3	6,162	1,567	0	0

This Document Last Updated : OCT 22, 2020

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.