

IMPORTANT SAFETY RECALL

This INTERIM notice applies to your vehicle,

VIN: Headlamp Aiming NHTSA Recall #18V906

Mercedes-Benz USA, LLC

Christian Treiber Vice President Customer Services

February, 2019



Dear Mercedes-Benz Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Daimler AG ("DAG"), the manufacturer of Mercedes-Benz vehicles, has decided that certain Model Year ("MY") 2018 C-Class vehicles fail to conform to Federal Motor Vehicle Safety Standard ("FMVSS") number 108 (Lamps, Reflective Devices, and Associated Equipment). Our records indicate that your vehicle is included in the affected population of vehicles.

What is the Concern?

On certain C300 and C300 4MATIC vehicles (205 platform), the low beam headlamp setting may not correspond to current production specifications. As a result, the headlamp setting may not comply with the requirements of Federal Motor Vehicle Safety Standard 108. If the low beam headlight is not properly adjusted, it could reduce visibility of the roadway, increasing the risk of a crash.

To remedy this issue, an authorized Mercedes-Benz dealer will check the headlights and adjust them if necessary. Unfortunately the remedy is currently not yet available.

We are working to correct this condition as quickly as possible. When the remedy becomes available, we will send you another letter asking you to take your vehicle to an authorized Mercedes-Benz dealer to have the recall completed free of charge.

Should you have any concerns or questions regarding your vehicle before you receive the next recall letter when the remedy is available, please contact an authorized Mercedes-Benz dealer. If for any reason a dealer is unable to address your questions or concerns, we are always happy to hear from you. Please contact us at 1-(800) FOR-MERCEDES (1-800-367-6372). A new vehicle identification number (VIN)-based recall lookup tool, on our MBUSA.com website, now offers a search function that will indicate whether a vehicle has been subject to a safety recall, and whether that vehicle has had the free remedy performed. Please visit www.MBUSA.com/recall.

If you are no longer the vehicle owner, or have a change of address, please complete the reverse side of this letter and return the complete letter in the enclosed envelope. If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 days to comply with federal regulations.

If an authorized Mercedes-Benz dealer for any reason is unable to remedy the situation without charge, or within a reasonable amount of time, pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153); or go to http://www.safercar.gov.

We regret any inconvenience this situation may cause you.

Sincerely,

	RT	

VIN:

plac	e in	the		OSE	D EN	IVEL	.OPE									E OF A												
■ EXPORTED■ LEASE, VEHICLE RETURNED■ SCRAPPED												SOL STO OTH	LEN															
☐ NEW OWNER INFORMATION												☐ MY NEW NAME OR ADDRESS IS:																
La	st Na	me,	First	Nam	е	ı	1	1	1				ı			1	ı	1				1					1	
Street										ı			1	1	1	1					Ар	t	I	1				
City											1	1		I				St	ate		ZIF)	<u> </u>					
Em	ail A	ddre	SS	I		1	1		1						1			1										
Ph	one (num	bers	only)	<u> </u>	I	1	1	1	<u> </u>		1	1	J	Mok	oile (n	umbe	ers o	nly)	1			1	1	1	<u> </u>	<u> </u>	<u> </u>
Date				•	Sign	 natu	re	 																				

THANK YOU FOR YOUR COOPERATION