



U.S. Department of Transportation  
**National Highway Traffic Safety  
Administration**

1200 New Jersey Avenue SE  
Washington, DC 20590

February 26, 2019

Mr. Gerrit Hurenkamp  
Director of Engineering  
Arcimoto Inc  
2034 W. 2nd Ave  
Eugene, OR 97402

NEF-150JK  
18V-939

**Subject:** Seat May Collapse In The Event of A Crash

Dear Mr. Hurenkamp:

This letter serves to acknowledge Arcimoto Inc's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**

ARCIMOTO/FUV/2017-2018

**Mfr's Report Date:** December 31, 2018

**NHTSA Campaign Number:** 18V-939

**Components:**

SEATS

**Potential Number of Units Affected:** 22

**Problem Description:**

Arcimoto Inc (Arcimoto) is recalling certain 2017-2018 FUV motorcycles. In the event of a crash, the seat may not support the driver as intended, preventing the seatbelts from holding the driver in place.

**Consequence:**

If the driver is not properly secured, it can increase the risk of injury in a crash.

**Remedy:**

Arcimoto has notified all affected owners and the motorcycles are within the manufacturer's control. The remedy for this recall is still under development. Owners may contact Arcimoto customer service at 541-683-6293. Arcimoto's number for this recall is 7F7-W3A5M-12.

**Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.safercar.gov](http://www.safercar.gov).

Please update your recall filing with Arcimoto's plan for remedying this defect once it has been determined.

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

It is our understanding that notification to owners began prior to our review of the owner notification letter. Should it become necessary for Arcimoto to do a renotification, the follow-up notification must be submitted to this office for review and it must comply with the requirements of Part 577.5, "Notification pursuant to a manufacturer's decision" and Part 577.10, "Follow-up notification."


Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Jennifer Kruger who may be reached by phone at (202) 366-2461, or by email at [jennifer.kruger@dot.gov](mailto:jennifer.kruger@dot.gov). We look forward to working with you.

Sincerely,



Kareem Habib  
Acting Chief, Recall Management Division  
Office of Defects Investigations  
Enforcement