

Attn: Indian Motorcycle Dealers

Subject: Safety Bulletin I-19-01 Released

Key Actions & Timing: Please Read

Questions: Contact Indian Motorcycle Technical Service

Dear Indian Motorcycle Dealer,

Indian Motorcycle has identified a potential assembly concern affecting the black Clutch and Brake Lever Accessory Kit (PN: 2883795- 658), for use with Indian Scout, Scout Sixty and Bobber models. The assembly concern affects the brake lever portion of the kit, which may not have been assembled to specification. The free-play adjustment screw may not be correctly installed and can result in front brake drag, unintentional front brake application, and potentially locking of front wheel.

- Click [HERE](#) to view I-19-01
- Click [HERE](#) to view I-19-01 Dealer FAQs

Thank you for your attention.

Sincerely,

Indian Motorcycle Service