

***** IMPORTANT SAFETY RECALL *****
NHTSA Recall No. 19E-020

March 7th 2019

██████████
Navistar Inc.
2701 Navistar Drive
Lisle, IL 60532

Dear ██████:

We are writing to inform you that Cummins Inc. has determined that a safety-related defect exists in certain B6.7 engines that were manufactured between December 14, 2016 and February 25, 2019. Cummins has initiated a recall of the subject engines. Our records indicate that some of these engines have been shipped to you.

A copy of Cummins' initial Part 573 Defect Notification report is enclosed. This notification was submitted to the National Highway Traffic Safety Administration (NHTSA) on March X, 2019. As more fully described in the Defect Notification, internal arcing within the fuel heater on the engine may create sufficient heat inside the fuel heater to cause plastic in the fuel heater to melt and potentially catch fire. It may also cause an engine stall.

Enclosed is a list of Engine Serial Numbers for affected engines that our records indicate were shipped to your plants. For engines installed in vehicles that have left your control, we encourage you to make a safety defect determination in accordance with 49 USC 30118 *et seq.* and, as appropriate, to submit a Defect Notification to NHTSA in accordance with 49 CFR Part 573. Cummins will conduct the recall, including notifying owners pursuant to 49 CFR Part 577, performing the remedy, and submitting quarterly status reports to NHTSA. Cummins is requesting that you provide the associated vehicle model identification, VINs and owner contact information to facilitate owner notification. Please work with your Cummins account team leader to ensure that the requested information is provided to Cummins as soon as possible.

For engines/vehicles that are still in your inventory, please contact the Customer Quality Assurance representative at the Rocky Mount Engine Plant to arrange for repairs. Please note that Federal law prohibits delivery of these engines, or vehicles equipped with these engines, under a sale or lease until this condition has been remedied.

Cummins is working to determine the field remedy and will communicate this as soon as it is available.

Cummins apologizes for this inconvenience, but we are initiating this action in the interest of our customers' safety and satisfaction with our products. Thank you for your assistance.

Please confirm receipt of this communication.

Sincerely,



Cummins Inc.

Enclosures:

1. Cummins Part 573 Defect Notification
2. List of Engine Serial Numbers.