

GLOBAL SAFETY FIELD INVESTIGATIONS  
DCS5017  
URGENT - DISTRIBUTE IMMEDIATELY

Date: April 16, 2019

Subject: Hard Tri-fold Tonneau Covers

Models: 2019 Chevrolet Silverado 1500 (New Model)  
2019 GMC Sierra 1500 (New Model)

To: All General Motors Dealers

**Stop Part Install/Sell/Delivery Order**

An attachment issue is being investigated with the Hard Tri-fold Tonneau Covers (RPO - VOZ):

- PN 84060327 Hard Tri-fold Tonneau Cover for Standard Bed.
- PN 84060328 Hard Tri-fold Tonneau Cover for Short Bed.

**Do Not Install** and/or **Sell** the parts listed above (quarantine and hold all parts in inventory).

**Do Not Deliver** vehicles with these parts installed until further notice.

We apologize for any inconvenience that this issue has caused. Additional information will be provided as soon as it becomes available.

Thank you for your cooperation.

END OF MESSAGE  
GLOBAL SAFETY FIELD INVESTIGATIONS