

U.S. Department of Transportation

National Highway Traffic Safety Administration

July 26, 2019

Mr. Kellen Russell DLT, LLC 7337 SW Tech Center Drive Portland, OR 97223

1200 New Jersey Avenue SE Washington, DC 20590

NEF-150KL 19E-044

Subject: Shifter Shaft May Break

Dear Mr. Russell:

This letter serves to acknowledge DLT, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

FIAT/500/2011-2019 CRAVENSPEED/SHIFTER SHAFT/9999

Mfr's Report Date: July 3, 2019

NHTSA Campaign Number: 19E-044

Components:

POWER TRAIN: MANUAL TRANSMISSION: FLOOR SHIFT ASSEMBLY

Potential Number of Units Affected: 740

Problem Description:

DLT, LLC. is recalling certain CravenSpeed Fiat Short Shifter shafts sold for use in 2011-2019 Fiat 500 vehicles. The Shifter Shaft may have been improperly manufactured with a through hole for the set screw rather than a blind hole, which may lead to the breakage of the Shifter Shaft.

Consequence:

If the shifter breaks while the vehicle is in motion, it can increase the risk of a crash.

Remedy

DLT has notified owners, and will provide a complete replacement shifter assembly with an updated shaft, free of charge. The recall began July 24, 2019. Owners may contact DLT customer service at 1-503-505-6886.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



NHTSA is missing critical, required information for this safety recall. This information must be supplied through the NHTSA Recalls Portal within 5 working days of confirming its accuracy:

- A statement that the defect or noncompliance can cause a vehicle crash without prior warning; (49 CFR 577.5 (f)(1)).

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Kristin Lepper who may be reached by phone at 202-366-5227, or by email at kristin.lepper@dot.gov. We look forward to working with you.

Sincerely,

Joshua Neff

Chief, Recall Management Division Office of Defects Investigations

Enforcement

