



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

August 12, 2019

Ms. Debbie Kauffman
MORryde International, Inc.
1966 Sterling Avenue
Elkhart, IN 46516

NEF-150KL
19E-051

Subject: Battery Tray may Separate from F-550 Frame

Dear Ms. Kauffman:

This letter serves to acknowledge MORryde International, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MORRYDE/F-550 BATTERY TRAY/9999

Mfr's Report Date: July 31, 2019

NHTSA Campaign Number: 19E-051

Components:

EQUIPMENT

Potential Number of Units Affected: 187

Problem Description:

MORryde International, Inc. (MORryde) is recalling certain battery trays sold for installation on Ford F-550 chassis. The battery trays may have inadequate welds, allowing the battery tray to detach from the chassis.

Consequence:

If the battery tray detaches from the chassis, contents of the tray may fall out and become road hazard, and the battery may discharge. Either scenario increases the risk of a crash.

Remedy:

MORryde will notify the vehicle manufacturers the purchased the trays, and dealers for those manufacturers will install additional weld areas on both sides of the battery tray for additional support, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact MORryde customer service at 1-574-293-1581.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please supply a list of the vehicle manufacturers that purchased the affected chassis including the quantity that each purchased.

NHTSA is missing critical, required information for this safety recall. This information must be supplied through the NHTSA Recalls Portal within 5 working days of confirming its accuracy:

- A description of the manufacturer's program for remedying the defect or noncompliance (49 CFR 573.6 (c)(8)(i)).
- Your company's program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of your company's notification of owners, purchasers and dealers, in accordance with § 573.13 of this part. Your company's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by § 573.13 that is not in a general reimbursement plan shall be submitted in your company's report to NHTSA under this section. If your company submits one or more general reimbursement plans, your company shall update each plan every two years, in accordance with § 573.13. Your company's remedy program and reimbursement plans will be available for inspection by the public at NHTSA headquarters (49 CFR 573.6 (c)(8)(i)). If the vehicles are new and would be covered under the manufacturer's warranty program, please state that in the remedy section of your filing.
- Your company must supply the estimated date(s) for which it will notify dealers and/or distributors regarding this safety recall. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefore, and furnish a revised estimate. (49 CFR 573.6 (c)(8)(ii)).

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Kristin Lepper who may be reached by phone at 202-366-5227, or by email at kristin.lepper@dot.gov. We look forward to working with you.

Sincerely,



Joshua Neff
Chief, Recall Management Division
Office of Defects Investigations
Enforcement