



TAP Worldwide, LLC d/b/a/ Transamerican Auto Parts  
400 West Artesia Boulevard  
Compton, California 90220 USA  
1-800-776-0767 ext. 1717

## **IMPORTANT SAFETY RECALL**

This notice applies to extended thread lug nuts, part numbers PXA16148; PXA16148B; and PXA16148OET.

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Date: November 27, 2019

Dear Valued TAP Dealer,

### **REASON FOR NOTICE**

TAP Worldwide, LLC has decided that a defect which relates to motor vehicle safety exists in TAP Worldwide, LLC extended thread lug nuts. The particular extended thread lug nuts, due to their diameter, may not seat properly when used with certain aftermarket wheel brands and models.

Specifically, if the subject extended thread lug nuts were used in connection with certain wheel models that featured smaller diameter lug nut holes, the lug nuts may interfere with the lug nut hold, failing to retain torque, which could potentially allow the wheel to come loose or detach from the vehicle, resulting in a crash.

### **WHAT SHOULD YOU DO**

You should contact TAP Worldwide, LLC's Recall Parts Assistance Department at 1-800-776-0767 ext. 1717 or by email at [recallpartsassistance@4wp.com](mailto:recallpartsassistance@4wp.com) immediately for more information regarding this recall and the assistance we ask of you. TAP Worldwide, LLC will remedy the defect without charge and at no cost to the dealer. Replacement parts are currently available.

TAP Worldwide, LLC requests your assistance in identifying customers that were sold the affected extended thread lug nuts. If customers are identified, contact TAP Worldwide, LLC Recall Parts Assistance Department at 1-800-776-0767 ext. 1717 or by email at [recallpartsassistance@4wp.com](mailto:recallpartsassistance@4wp.com) with the following information:

- Customer's name, address, and phone number
- Quantity of extended thread lug nuts sold to that customer
- Date of sale

TAP Worldwide, LCC also requests your assistance in removing, returning, and replacing affected extended thread lug nuts. We are requesting you remove all affected extended thread lug nuts. We are replacing the affected extended thread lug nuts with a new extended thread lug

nuts. If a customer has already replaced an extended thread lug nuts that is included in this recall and is seeking reimbursement, please refer them to the reimbursement plan included in their customer notification or they may contact Recall Parts Assistance Department at 1-800-776-0767 ext. 1717 for assistance.

TAP Worldwide, LLC requests you remove and return all affected extended thread lug nuts to us. Credit will be issued once the recall parts have been received, inspected, and verified. TAP Worldwide, LLC will issue a full credit for the part returned from inventory, plus shipping costs. Please ship parts to:

TAP Worldwide, LLC  
Attn: Recall Parts Assistance  
400 West Artesia Boulevard  
Compton, California 90220

Please be advised that it is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment covered by the notification under a sale or lease until the defect is remedied.

If you have any questions regarding this matter, please contact us at 1-800-776-0767 ext. 1717.

Sincerely,

TAP Worldwide, LLC