



# Service Bulletin

American Honda Motor Co., Inc.

Monkey 125/A #1  
ISSUED: OCTOBER 2019

## ACCESSORY SAFETY RECALL

### Monkey 125/A - Rear Carrier

Honda is launching a SAFETY RECALL on the accessory Rear Carrier for Monkey 125/A motorcycles due to a potential defect that may allow the Rear Carrier to fall off the motorcycle while riding. A Rear Carrier that falls into the roadway poses a safety hazard to other roadway users.

Effective immediately, YOU MUST NOT SELL the following Accessory Rear Carrier:

08L70-K0F-A00 - Rear Carrier

#### SERVICE BULLETIN

*Service Bulletin Monkey 125/A #1*, which includes Safety Recall information, parts information, and warranty claim information will be available October 28, 2019.

#### PARTS INFORMATION

All dealers with affected accessory inventory must not sell or install the affected part. Dealers must immediately remove any Rear Carrier already installed onto a dealer-owned motorcycle. Make sure the above part number is removed from any Internet parts advertising by your dealership. A replacement part will not be offered. Dealer parts return and customer refund information will be provided October 28, 2019.

#### CUSTOMER NOTIFICATION

AHM intends to mail customer letters to all owners of a Monkey 125/A motorcycle as early as possible, subject to State registration information. Customers will be informed that their motorcycle may be affected by a Rear Carrier with a safety related defect and advised to discontinue using the Rear Carrier. Customers will also be informed that a refund will be offered in lieu of a replacement part.

#### **Make sure all departments in your dealership are aware of this action.**

Honda will update dealers with any new information as it becomes available.

If you have any questions, please contact TechLine or your District Service Manager.