

# Part 573 Safety Recall Report

# 19E-082

**Manufacturer Name :** Zamzow Mfg Co Inc

**Submission Date :** DEC 03, 2019

**NHTSA Recall No. :** 19E-082

**Manufacturer Recall No. :** NR



## Manufacturer Information :

**Manufacturer Name :** Zamzow Mfg Co Inc

**Address :** 3201 N Broadway

St Louis MO 63147

**Company phone :** 816-483-5213

## Population :

**Number of potentially involved :** 1

**Estimated percentage with defect :** 100 %

## Equipment Information :

**Brand / Trade 1 :** AERO EASY COVER TARPING S

**Model :** ALL MANUAL

**Part No. :** 0311-960728

**Size :** NR

**Function :** NR

**Descriptive Information :** AERO INDUSTRIES FOUND THAT THEIR PAWL ASSEMBLY DID NOT HAVE THE PIN TACK WELDED TO THE PAWL

**Production Dates :** NOV 11, 2018 - APR 19, 2019

## Description of Defect :

**Description of the Defect :** Pawl Assembly (0311-960728) is used in all Aero Industries Easy Cover Manual Crank Assemblies. During the Pawl Assembly assembling process the Spring Return Pin (0835-691715) must be tack welded to the bottom of the Pawl.

**FMVSS 1 :** NR

**FMVSS 2 :** NR

**Description of the Safety Risk :** Pawl Assembly could dis-engage from Hub on Manual Crank Assembly. Disengagement could cause Swing Arms on Easy Cover tarping system to swing to the back of the dump body.

**Description of the Cause :** Tack welding of the Spring Return Pin to the Pawl did not occur during the assembly process.

**Identification of Any Warning that can Occur :** Swing Arms on Easy Cover tarp system could swing to back of dump body that can Occur : uncontrollable.

**Supplier Identification :****Component Manufacturer**

Name : Tomlinson Manufacturing Company, Inc.  
Address : 2457 East Washington Street  
SUITE B INDIANAPOLIS INDIANA 46201  
Country : United States

**Chronology :**

4/20/19 AERO IND. RECIEVED A REPORT FROM A CUSTOMER THAT THE PIN WAS COMING OUT OF THE PAWL ASSEMBLY. AERO REVIEWED IT'S INVENTORY AND FOUND THE SUPPLIER HAD ELIMINATED A TACK WELD ON THE ASSEMBLY.AERO IND. THEN CREATED A CORRECTIVE ACTION REPORT#33852.

**Description of Remedy :**

Description of Remedy Program : ZAMZOW MFG. CO INC. WAS CONTACTED BY AREO IND. AND NOTIFIED THAT THE KANSAS CITY LOCATION HAD PURCHASED A REPLACEMENT PART FOR A CUSTOMER FROM THE DEFECTED BATCH

How Remedy Component Differs from Recalled Component : AERO IND. SENT OUT A PAWL RECALL RETROFIT KIT (0311-969101)

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : OWNER FIRST NOTIFIED 9/24/19. PART REPLACED ON 10/18/19. RECALLED PART RETURNED TO AERO IND.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

**Purchaser Information :**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : MORALES TRUCKING

Address : 1409 E 123 RD ST  
OLATHE KS 66061

Country : US

Company Phone : 9132019229

\* NR - Not Reported