

Supersession Chain Break

To: SDC EST CEN WST

From: Parts Pricing

Department: Parts Department

Date: 2019-06-14 11:48

Category: Parts/Service

To ensure the safety of all our customers, the decision has been made to remove the Inflator parts from ALL Takata Recall part supersession chains. It is **EXTREMELY IMPORTANT** that you update your DMS system with the following information regarding these Takata Airbag supersession chain breaks:

Original chain was:
98279AE00A (22) --> 98279AE04A (21)

NEW:
98279AE04A (11) Stand Along
98279AE00A (12) OBSOLETE

Original Chain was:
98279AG00A (22) --> 98279AG05A (32) --> 98279AG05B (31)

NEW:
98279AG05A (32) --> 98279AG05B (31)
98279AG00A (12) OBSOLETE

Original chain was:
98279AJ02A (22) --> 98279AJ06A (21)

NEW:
98279AJ06A (11) Stand Along
98279AJ02A (12) OBSOLETE

Original chain was:
98279FE000 (22) --> 98279FE070 (21)

NEW:
98279FE070 (11) Stand Along
98279FE000 (12) OBSOLETE

Original chain was:
98279FE160 (22) --> 98279FE12A (21)

NEW:
98279FE12A (11) Stand Along
98279FE160 (12) OBSOLETE

Original Chain was:
98279FG010 (22) --> 98279FG07A (32) --> 98279FG07B (31)

NEW:
98279FG07A (32) --> 98279FG07B (31)
98279FG010 (12) OBSOLETE

Original Chain was:
98279SC010 (22) --> 98279SC05A (32) --> 98279SC05B (31)

NEW:
98279SC05A (32) --> 98279SC05B (31)
98279SC010 (12) OBSOLETE

If you have any questions about this information, please refer to the Part Inquiry screen in RPM or contact the Parts Information Coordinators.

Thank you