



5 Stan Perkins Road Spartanburg, South Carolina 29307 USA 864-327-4744
www.kymcousa.com

VOLUNTARY SAFETY RECALL

February 2019

NHTSA Recall# 19V036

Voluntary Safety Recall: KYMCO Like 200i, Potential leaking from fuel line connection.

Dear KYMCO Dealer,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Defect Involved:

Kwang Yang Motor Co., Ltd. (KYMCO) is voluntarily recalling select 2018 model year “Like 200i” units. These units have a potential for leakage from the high-pressure fuel line due to loosening of the fuel line clamp after extensive operation resulting in a potential fire hazard.

Vehicles Involved and VIN Range:

Select 2018 model year Like 200i units (324 units total).

VIN Range of affected units:

LC2D2H128JC100371 through LC2D2H12XJC100694

Description of Defect:

Potential for leakage due to loosening of the fuel line clamp after extensive operation resulting in a potential fire hazard.

Plan of Action:

KYMCO USA, Inc. will send the repair kits to all authorized KYMCO dealers based on the number of affected units purchased to ensure that each dealer has an adequate quantity of kits on hand to perform the recall procedure in a timely manner. Additional repair kits are available upon request by the dealer.

KYMCO USA, Inc. will send letters to all registered owners (based off warranty registration with KYMCO USA, Inc.) of the affected units advising them of this



5 Stan Perkins Road Spartanburg, South Carolina 29307 USA 864-327-4744
www.kymcousa.com

voluntary recall and instructing them to make appointments for the repair of their vehicle at any authorized KYMCO dealer as soon as possible. Please schedule the repairs for the owners as soon as possible to prevent any risk as a result of this defect. We have included with this letter a list of customers who have been registered with KYMCO USA, Inc. by your dealership in our warranty system with affected Like 200i units. Please advise KYMCO USA, Inc. if there are any outstanding customers who have not been warranty registered so we can contact them immediately.

The repair kit (Part number: Like200-2019-Recall-Adj) contains the following items:

- Torque Wrench (if needed)
- Repair Instructions
- Warranty/Reimbursement Instructions

Reimbursement for Recall:

KYMCO USA, Inc. will provide the recall repair kits free of charge and pay pre-established KYMCO dealer labor rates for each repair performed. If any required equipment/instrument is needed, that is not in dealers' possession, we will provide it to them free of charge. Kwang Yang Motor Co., Ltd. has assigned a flat rate code for this recall:

- Flat rate code: Like200-2019-Recall-Adj
- Flat rate time allotted: Thirty (30) minutes

For any further questions, please contact KYMCO USA, Inc.
Phone: (888) 909-6301
Email: like2002019recall@kymcousa.com

We apologize for any inconvenience caused by this voluntary recall.

Kindest regards,

KYMCO USA, Inc.