

# Part 573 Safety Recall Report

# 19V-041

**Manufacturer Name :** Heartland Recreational Vehicles, LLC**Submission Date :** JAN 17, 2019**NHTSA Recall No. :** 19V-041**Manufacturer Recall No. :** 99.01.46**Manufacturer Information :****Population :**

Manufacturer Name : Heartland Recreational Vehicles, LLC

Number of potentially involved : 14

Address : 1001 All Pro Drive

Estimated percentage with defect : 100 %

Elkhart IN 46514

Company phone : 8772628032

**Vehicle Information :**

Vehicle 1 : 2019-2019 Heartland Prowler &amp; Trail Runner

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

**Descriptive Information :** It has been decided the vehicles in this recall population may have been manufactured with ST225/75R15 Load Range D Tires rated for 2540 lbs. instead of ST225/75R15 Load Range E Tires rated for 2860 lbs. This insufficient load range tires were inadvertently changed with other lower rated campers.

Production Dates : OCT 08, 2018 - NOV 30, 2018

VIN Range 1 : Begin : 5SFPB3429KE407825 End : 5SFEB3422KE410539  Not sequential**Description of Defect :**

**Description of the Defect :** It has been decided the vehicles in this recall population may have been manufactured with ST225/75R15 Load Range D Tires rated for 2540 lbs. instead of ST225/75R15 Load Range E Tires rated for 2860 lbs. This insufficient load range tires were inadvertently changed with other lower rated campers.

FMVSS 1 : NR

FMVSS 2 : NR

**Description of the Safety Risk :** An overloaded tire leads to an increased risk of tire failure, property damage and/or vehicle crash.

**Description of the Cause :** Wrong tires ST225/75R15D were installed instead of ST225/75R15E.

**Identification of Any Warning that can Occur :** NR

**Supplier Identification :****Component Manufacturer**

Name : NR  
Address : NR  
NR  
Country : NR

**Chronology :**

On January 11, 2019 purchasing notified me that they had discovered an error that had occurred due to a change in Wheel style on PCN 6189. It was identified that the change caused these units to have incorrect tires installed when the unit had 5100lb axles. The safety committee met on January 16, 2019 and agreed a recall be issued.

**Description of Remedy :**

Description of Remedy Program : The remedy is to replace the tires with the correct ones supplied by Heartland.  
How Remedy Component Differs from Recalled Component : The Replacement tires are rated for the vehicles GAWR.  
Identify How/When Recall Condition was Corrected in Production : January 11, 2019 specifications were correcting in the computer system, none were currently in production.

**Recall Schedule :**

Description of Recall Schedule : Heartland will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.  
Planned Dealer Notification Date : FEB 18, 2019 - FEB 18, 2019  
Planned Owner Notification Date : MAR 18, 2019 - MAR 18, 2019

\* NR - Not Reported