## OMB Control No.: 2127-0004

## **Recall Quarterly Report**

19V-045

**Manufacturer Name:** Trail King Industries, Inc.

NHTSA Recall No. / MFR Recall No. : 19V-045 /TK201901

**Recall Subject :** Fifth Wheel Coupler Plate may Crack **Owner Notification Beginning Date :** MAR 01, 2019

Owner Notification End Date: APR 01, 2019



| Report # | Submission Date | Report<br>Quarter | Recall<br>Population | Total<br>Remedied | Total<br>Unreachable | Total<br>Removed |
|----------|-----------------|-------------------|----------------------|-------------------|----------------------|------------------|
| 2        | JUL 23, 2019    | 2019-2            | 80                   | 12                | 0                    | 0                |
| 1        | APR 12, 2019    | 2019-1            | 80                   | 9                 | 0                    | 0                |

This Document Last Updated: JUL 24, 2019

## **Definitions:**

 $Report\ Quarter:\ The\ quarter\ the\ manufacturer\ is\ reporting\ recall\ completion\ figures\ (e.g.\ 2012-3\ means\ the\ 3^{\bf rd}\ quarter\ of\ 2012).$ 

Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.