

AKA1 Stop Sale - Re-programming instrument cluster

Version 7

Update 7/3/19

Please note, due to a data error within the latest **PIWIS Tester software version 38.500.010** it is **not possible to program the software versions 0144, 0311 and 0218** during this campaign.

This data error will be fixed with the next **PIWIS Tester software version 38.500.020**. The update will be available online latest by Friday, 5th of July 2019.

Update 4/5/19

A revised TI is now attached to this post.

Update 3/8/19

The AKA1 TI is now attached to this post.

Update 2/20/19:

The VIN list is now attached to this post.

Stop Delivery

Vehicles must not be delivered to customers until the required remedial measure has been carried out. Information on the repair procedure will be forthcoming.

Overview

Due to a missing assignment within the software of the instrument cluster, there is no link between brake pad wear indicator and brake warning light.

Due to that, only the yellow Information Message "Brake pads worn" will be shown in the multi-functional display of the instrument cluster when brake pads are worn. An additional and permanent red brake warning light will not be displayed.

To ensure that the prescribed warning light will be displayed when the wear limit of the brake pads is reached, the instrument cluster has to be re-programmed with an updated software.

Model type	Panamera (971)
Model year	from 2017 to 2019
Manufacturing period	Between 03.21.2016 and 11.15.2018
Number of affected vehicles	TBD

Vehicle usage

Affected vehicles may only be driven for loading and unloading purposes in the transport chain. You may check the status of the affected vehicle by accessing PIWIS Vehicle Information.

Remedial measures

A remedial measure for re-programming the instrument cluster is currently in preparation and will be made available as soon as possible.

For any questions, please contact external.mitchell.grasser@porsche.us

[971 9 11-19 AKA1 Re-Program Instrument Cluster v2.pdf](#)

115.9 KB

(983 views)

[AKA1_VIN_list_USA.xlsx](#)

423.1 KB

(691 views)

Created by [Jim Moore](#) on Feb 15, 2019 8:32 PM. Last modified by [Ryan Cooney](#) on Jul 3, 2019 2:04 PM.

Categories: Recalls, Panamera, Stop Sale

Tags : [instrument cluster](#), [aka1](#)

7509 Views

[Report Abuse](#)

Content and Topics

Your Groups >

Your Content >

Your Places >

Personal

Edit Profile >

Change Password >

Manage

Admin Console >

PPN Administration >

Create

Discussion >

Files >

Document >

Collaboration >

Document

Blog Post >

Poll >

Message >

Event >

Photo Album >

Idea >

Space >

© 2019 Dr. Ing. h.c. F. Porsche AG. Legal notice. Copyright. Terms of use. Privacy Policy. Cookie Policy. 010