

IMPORTANT SAFETY RECALL 2019030009

This UPDATED notice applies to your vehicle,

Rework Rear Tail Lamp NHTSA Recall # 19V131 Mercedes-Benz USA, LLC Christian Treiber Vice President Customer Services

April, 2019



- . A remedy is available for your vehicle.
- Schedule an appointment with your authorized Mercedes-Benz dealer as soon as possible.
- This repair will be provided free of charge.

Dear Mercedes-Benz Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Daimler AG ("DAG"), the manufacturer of Mercedes-Benz vehicles, has decided that a defect which relates to motor vehicle safety exists in certain Model Year ("MY") 2018 CLA-Class vehicles. Our records indicate that your vehicle is included in the affected population of vehicles.

What is the CONCERN?

What will your DEALER DO?

DAG determined that on certain MY 2018 CLA-Class vehicles (117 platform), the electrical contact of the tail lamps might be impaired. An impaired electrical connection of the tail lamps could cause the tail lamps to flicker or fail to illuminate completely. Impaired lighting of the vehicle could reduce visibility, increasing the risk of a crash.

An authorized Mercedes-Benz dealer will replace the rear bulb sockets in the affected vehicles. <u>This service will be provided free of charge</u>. We are dedicated to always delivering the best customer experience, and respect for your time is a top priority. While the minimum repair time can be up to **30 minutes**, your dealer can provide you with a better estimate of the overall time for this service visit. As a matter of normal service process, an authorized Mercedes-Benz dealer will also check for other repair measures which might be applicable to your vehicle and this may increase the required working time.

What should YOU DO?



To find the most convenient authorized Mercedes-Benz dealer from your smartphone, scan the QR code to the

Information for Owners

For additional information and to schedule an appointment, please contact your preferred authorized Mercedes-Benz dealer at your earliest convenience. To locate authorized dealers see www.mbusa.com/recall. Please mention you are scheduling an appointment to replace the rear bulb sockets under Recall Campaign #2019030009.

You may be asked for your 17-digit Vehicle Identification Number (VIN) which for your convenience is located above your name at the top of this letter.

In the event that you are no longer the vehicle owner, or have had a change of address, please complete the reverse side and return the updated information in the enclosed envelope.

If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 business days to comply with Federal Regulations.

A VIN-based recall lookup tool on our MBUSA.com website now offers a search feature that will indicate whether a vehicle has been subject to a safety recall, and whether that vehicle has had the free remedy performed. See www.mbusa.com/recall. Should you have any questions or encounter any difficulty regarding this Recall Campaign, please contact an authorized Mercedes-Benz dealer. If for any reason a dealer is unable to remedy your situation, we are always happy to hear from you. Please contact us at 1-(800) FOR-MERCEDES (1-800-367-6372).

If an authorized Mercedes-Benz dealer for any reason is unable to remedy the situation without charge, or within a reasonable amount of time, pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153); or go to http://www.safercar.gov.

We apologize for any inconvenience this situation may cause you.

Che. Tush

Sincerely,

Mercedes-Benz USA, LLC

A Daimler Company One Mercedes-Benz Drive Sandy Springs, GA 30328 Phone (770) 705-0600

MPORTANT	VIN:
----------	------

	NCLO	SED																											place i e may
	EXTORTED									SOLD STOLEN OTHER																			
	□ NEW OWNER INFORMATION														☐ MYNEW NAMEORADDRESSIS:														
Las	st Nan	ne, Fir	st Nan	ne								1																	
Str	eet																									Ap	t		
Cit	у																					Sta	te		ZIP				
Em	ail Ad	dress																											
Pho	one (n	ıumbeı	s only	')		1	1		1			1				Mobil	e (nun	nbers	only)		l	I	1	ı	1	1			
Date								Sign	atur	re																			