

SRAN560 – HEADSTOCK TIDY RECALL

Follow-up SMS Campaign – Launched 10th December 2019

NHTSA Campaign No: 19V133

Transport Canada Campaign No: 2019096

SMS MESSAGE SENT TO THE OWNERS

Dear Triumph Owner please visit the below link for important safety recall information.

<http://mpage.info/SB560>

Reply STOP to cancel msg&data rates may apply

DETAILS ON LANDING PAGE (<http://mpage.info/SB560>)

TRIUMPH

Your Triumph Motorcycle has been identified as having an important open safety recall.

- DETAILS

The clutch cable of your motorcycle may contact the main harness sheath and cause damage to wiring within the main harness. If this condition occurs and remains undetected it may lead to a loss of electrical power and increase your risk of an accident.

+ REMEDY

+ WHAT TO DO NEXT

TRIUMPH

Your Triumph Motorcycle has been identified as having an important open safety recall.

+ DETAILS

- REMEDY

Your preferred Triumph dealer will remedy this with replacement of the head-stock tidy at no cost to you.

+ WHAT TO DO NEXT

TRIUMPH

Your Triumph Motorcycle has been identified as having an important open safety recall.

+ DETAILS

+ REMEDY

- WHAT TO DO NEXT

To ensure your maximum safety, we require your co-operation to ensure your motorcycle is modified without delay. Please contact your local or preferred Triumph dealer immediately to book your motorcycle in for the recall work to be carried out free of charge. To find your dealer, please use our Find A Dealer search at <https://www.triumphmotorcycles.com/dealers/find-a-dealer>