

**Recall Quarterly Report****19V-136****Manufacturer Name :** Daimler Trucks North America LLC**NHTSA Recall No. / MFR Recall No. :** 19V-136 /FL-810**Recall Subject :** ABS Malfunction Light may not Reactivate**Owner Notification Beginning Date :** APR 26, 2019**Owner Notification End Date:** APR 26, 2019

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	OCT 30, 2019	2019-3	14	3	0	0
1	AUG 05, 2019	2019-2	14	3	0	0

This Document Last Updated : NOV 06, 2019

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.