



U.S. Department of Transportation  
**National Highway Traffic Safety  
Administration**

1200 New Jersey Avenue SE  
Washington, DC 20590

April 5, 2019

Mr. Charles Smart  
Head of Claims Management Dept  
Triumph Motorcycles America, LTD  
100 Hartsfield Centre Parkway  
Suite 200  
Atlanta, GA 30354

NEF-150JK  
19V-167

**Subject:** Coolant Leak Near Rear Tire

Dear Mr. Smart:

This letter serves to acknowledge Triumph Motorcycles America, LTD's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**  
TRIUMPH/SPEED TWIN/2019

**Mfr's Report Date:** March 5, 2019

**NHTSA Campaign Number:** 19V-167

**Components:**  
ENGINE AND ENGINE COOLING:COOLING SYSTEM:HOSE

**Potential Number of Units Affected:** 726

**Problem Description:**  
Triumph Motorcycles America, LTD (Triumph) is recalling certain 2019 Speed Twin motorcycles. Improper routing of the coolant hose may cause it to contact the exhaust header pipe, damaging the hose and resulting in a coolant leak near the rear tire.

**Consequence:**  
Loss of coolant near the rear tire may cause a loss of traction, increasing the risk of crash.

**Remedy:**  
Triumph will notify owners, and dealers will inspect the coolant hose routing, rerouting the hose and replacing it if necessary, free of charge. The recall is expected to begin in April 2019. Owners may contact Triumph customer service at 1-678-854-2010. Triumph's number for this recall is SRAN563.

**Notes:**  
Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.safercar.gov](http://www.safercar.gov).

We have received Triumph's proposed owner notification letter and have approved it for distribution after our edits have been incorporated.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Jennifer Kruger who may be reached by phone at (202) 366-2461, or by email at [jennifer.kruger@dot.gov](mailto:jennifer.kruger@dot.gov). We look forward to working with you.

Sincerely,



Kareem Habib  
Acting Chief, Recall Management Division  
Office of Defects Investigations  
Enforcement