

U.S. Department of Transportation

National Highway Traffic Safety Administration

April 8, 2019

Mrs. Nancy Stone Honda (American Honda Motor Co.) 1919 Torrance Blvd Torrance, CA 90501

1200 New Jersey Avenue SE Washington, DC 20590

NEF-150SS 19V-256

Subject: Posisble Loss of a Tailgate Lid Light

Dear Mrs. Stone:

This letter serves to acknowledge Honda (American Honda Motor Co.)'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

## Makes/Models/Model Years:

ACURA/MDX/2014-2019 ACURA/MDX SPORT HYBRID/2017-2019

Mfr's Report Date: March 28, 2019

NHTSA Campaign Number: 19V-256

**Components:** 

EXTERIOR LIGHTING
EXTERIOR LIGHTING:TAIL LIGHTS

**Potential Number of Units Affected:** 322,897

### **Problem Description:**

Honda (American Honda Motor Co.) is recalling certain 2014-2019 Acura MDX and 2017-2019 Acura MDX Sport Hybrid vehicles. Moisture may enter the tailgate lid lights, possibly causing a loss of the tailgate lid lights and the tailights.

#### **Consequence:**

Loss of the taillights reduces the vehicle's visibility, increasing the risk of crash.

# Remedy:

Honda will notify owners, and dealers will modify the tailgate lid lights and install updated gaskets and a wiring sub-harness or will replace both tailgate lid lights. The repairs will be performed free of charge. The recall is expected to begin on April 29, 2019. Owners may contact Honda customer service at 1-888-234-2138. Honda's number for this recall is M49.

#### **Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to Honda's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Shiver who may be reached by phone at (202) 366-7401, or by email at sarah.shiver@dot.gov. We look forward to working with you.

Sincerely,

Kareem Habib

Acting Chief, Recall Management Division

aslan Adul

Office of Defects Investigations

Enforcement

