OMB Control No.: 2127-0004

Part 573 Safety Recall Report

Manufacturer Name :Precision IndustriesSubmission Date :APR 02, 2019NHTSA Recall No. :19V-268Manufacturer Recall No. :NR

Manufacturer Information :

Manufacturer Name : Precision Industries

Address : 524 S Business Rte 5 Camdenton MO 65020 Company phone : 5733468387

Population :

Number of potentially involved :3Estimated percentage with defect :100 %

Vehicle Information :

Vehicle 1: 2017-2018 Spartan Metrostar Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES Body Style: OTHER Power Train: DIESEL Descriptive Information: Looked at invoices of recalled Whelen part for the provided dates. Production Dates: DEC 04, 2017 - JUL 09, 2018 VIN Range 1: Begin: 4S7CT2D96JC084316 End: 4S7CT2D96JC084318 Not sequential

Description of Defect :

Description of the Defect :Brake light may falsely activate due to a floating voltageFMVSS 1 :NRFMVSS 2 :NRDescription of the Safety Risk :Drivers behind truck may think brake lights are being depressed when they are not actually.Description of the Cause :NRIdentification of Any Warning that can Occur :NR

Supplier Identification :

Component Manufacturer

Name : Whelen Engineering Company Inc

Address : 51 Winthrop Road Chester CONNECTICUT

The information contained in this report was submitted pursuant to 49 CFR §573



19V-268

Part	573	Safety	Recall	Report
------	-----	--------	--------	--------

Country :	United States
-----------	----------------------

Chronology :

NR

Description of Remedy :	
Description of Remedy Program :	Replace six lights with Whelen's recall replacement
How Remedy Component Differs from Recalled Component :	
Identify How/When Recall Condition was Corrected in Production :	NR

Recall Schedule :

Description of Recall Schedule :	Get replacement lights from Whelen and replace ASAP.
Planned Dealer Notification Date :	NR - NR
Planned Owner Notification Date :	NR - NR

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573