

Part 573 Safety Recall Report

19V-269

Manufacturer Name : Weis Fire & Safety**Submission Date :** APR 02, 2019**NHTSA Recall No. :** 19V-269**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Weis Fire & Safety

Address : 111 East Pacific Ave

Salina KS 67401

Company phone : 7858259527

Population :

Number of potentially involved : 1

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2018-2018 Ford F550 4X4 CREW CAB

Vehicle Type : LIGHT VEHICLES

Body Style : PICKUP TRUCK

Power Train : GAS

Descriptive Information : Weis received a Safety Recall Notice from Whelen via email on 08-29-18 concerning a defect in multiple brake light models. After reviewing our records we had only one customer that was affected by Whelen's recall.

Production Dates : MAY 08, 2018 - JUL 23, 2018

VIN Range 1 : Begin : 1FD0W5HY9JEC46423 End : 1FD0W5HY9JEC46423 Not sequential**Description of Defect :**

Description of the Defect : Whelen's brake light model # M6BTT may activate if there is a transient voltage on the brake input line (e.g., without further brake input), but can be returned to normal operation when a brake input is applied and then removed.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Whelen's brake light may activate if there is a transient voltage on the brake input line (e.g., without further brake input), but can be returned to normal operation when a brake input is applied and then removed.

Description of the Cause : Transient voltage on the input line.

Identification of Any Warning that can Occur : None.

Supplier Identification :

Component Manufacturer

Name : Whelen Engineering
Address : 51 Winthrop RD
Chester CONNECTICUT 06412
Country : United States

Chronology :

Weis received a Safety Recall Notice from Whelen via email on 08-29-18 concerning a defect in a multiple brake light models in addition to our customer contacting us stating there was an issue with the brake lights.

Description of Remedy :

Description of Remedy Program : Weis contacted Whelen for replacement M6BTT brake lights at no charge to replace their customer's defective/recalled ones.

How Remedy Component Differs from Recalled Component : Whelen part # M6BTT, M6 LED Brake/Tail/Turn light was replaced with production inventory that didn't fall into the production dates of November 1, 2017 and May 16th, 2018 per Whelen's Safety Recall.

Identify How/When Recall Condition was Corrected in Production : Weis worked with their customer Chief Mark Ryan @ Crawford Co Fire Dist # 1 and made sure the replacement brake lights from Whelen were installed and worked correctly in September 2018 and returned the defective M6BTT brake light to Whelen on 10-08-18.

Recall Schedule :

Description of Recall Schedule : Weis has already replaced the defective Whelen brake lights with their customer in September of 2018.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported