

**Recall Quarterly Report****19V-309**

**Manufacturer Name :** Daimler Vans USA, LLC  
**NHTSA Recall No. / MFR Recall No. :** 19V-309 /VS3FERNLI  
**Recall Subject :** High Beams May Not Deactivate by Switch  
**Owner Notification Beginning Date :** JUN 14, 2019  
**Owner Notification End Date:** JUN 14, 2019



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JUL 30, 2019	2019-2	1,517	244	0	0

This Document Last Updated : JUL 31, 2019

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).  
**Recall Population :** The total number of products recalled by the manufacturer.  
**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.  
**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.  
**Total Removed :** Products that have been scrapped, stolen, or exported.