

Part 573 Safety Recall Report

19V-345

Manufacturer Name : Supreme Corporation**Submission Date :** MAY 03, 2019**NHTSA Recall No. :** 19V-345**Manufacturer Recall No. :** NR**Manufacturer Information :****Population :**

Manufacturer Name : Supreme Corporation

Number of potentially involved : 278

Address : 2581 East Kercher Road
Goshen IN 46528

Estimated percentage with defect : NR

Company phone : 999

Vehicle Information :

Vehicle 1 : 2018-2019 Supreme Platform

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Supreme platform bodies with a tuckaway style lift gate.

Production Dates : JAN 01, 2018 - APR 18, 2019

VIN Range 1 : Begin : NR

End : NR

☐ Not sequential**Description of Noncompliance :**

Description of the Noncompliance : Due to placement of rear clearance lamp, certain units may not meet FMVSS 108 visibility requirements.

FMVSS 1 : 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2 : NR

Description of the Safety Risk : Due to lack of visibility of rear clearance lamp, there is an increased risk of rear impact.

Description of the Cause : Due to inconsistent practice between production plants, some clearance lamps were installed on the inboard side of the rear liftgate. This placement blocks part of the required 90-degree light spray, resulting in a noncompliance.

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR
Address : NR
NR
Country : NR

Chronology :

On or about April 18th 2019, an internal audit discovered that some vehicles were built with rear clearance lamps mounted on the inboard side of the rear liftgate. On April 23rd an exposure analysis began to determine the population of affected vehicles. On April, 26 2019 the Wabash National Product Safety Council convened and determined that a FMVSS noncompliance existed and decided to conduct a recall on affected vehicles.

Description of Remedy :

Description of Remedy Program : NR
How Remedy Component Differs from Recalled Component : NR
Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR
Planned Dealer Notification Date : MAY 31, 2019 - MAY 31, 2019
Planned Owner Notification Date : JUN 15, 2019 - JUN 15, 2019

* NR - Not Reported