



IMPORTANT SAFETY RECALL

**AUTOCAR, LLC SAFETY RECALL ACX-1905
NHTSA RECALL NO. 19V534**

July 2019

TO: U.S. Distributors
Dealer Principals, Service Managers, Warranty Managers, Parts Managers

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Autocar, LLC has determined that a defect that relates to motor vehicle safety exists in 23, 2019-2020 model year Xpeditor chassis. These chassis were manufactured between December 17, 2018 and May 2, 2019 with non-sequential serial numbers in the range 229098 through 230456. Accordingly, a recall to address this issue is being initiated effective July 8, 2019.

**MODELS
AFFECTED:** Autocar Xpeditor MY 2019-2020

**COMPONENTS
AFFECTED:** Service Brake quick release valve location

**SAFETY DEFECTS
AND POTENTIAL
RISKS:** The service brake quick release valve location is too far from the brake chamber and the vehicle would experience increased service brake release timing, increasing the risk of a crash, personal injury or property damage.

**REPAIR
REQUIRED:** The service brake quick release valves will be relocated to correct the release timing at no charge to the owner.

**REPAIR
AVAILABLE:** VIN profiles in the Autocar Warranty System will be updated to show the open recall on July 8, 2019 and a spreadsheet of the affected VINs will be available in the Warranty system.

REMINDER: It is a violation of Federal law to sell or lease a vehicle covered by this recall notice unless the recall remedy has been completed. Substantial civil penalties apply to violations of this law.

If you have any questions or concerns, please contact the Autocar Warranty Department at warranty@autocartruck.com.

Sincerely,

AUTOCAR, LLC

ACF 00002 Rev. 000