

## 2013-2016 MY RANGE ROVER RANGE ROVER SPORT Safety Recall N335 – Doors may not latch or open while driving



- Customers have reported the door is unlatched when in the closed position and no indication provided of an unlatched condition. Some customers have reported that one door has opened while the vehicle was in motion. Vehicle doors not latched in either the primary or secondary state may open during driving.
- Land Rover retailers will download the latest software. This software will disable the Unilatch Keyless Vehicle (KV) entry function on the vehicle.
- Vehicles in this recall have previously been included in recall P068 for a similar symptom.
- 65,387 USA vehicles are affected. Does not affect Canada
- Retailers were notified by Bulletin June 6<sup>th</sup> 2019
- Expected date for software delivery and the Technical repair bulletin is June 28<sup>th</sup> 2019.
- Customer mailing notification by July 19<sup>th</sup> 2019.
- All affected new vehicles have been retailed.