

AKB2 Recall campaign - Replacing fastening nuts of the drive shafts on the rear axle

Version 1

English (US)

- > Overview
- > Porsche Mobility
- > Parts required
- > Warranty processing
- > Further information

AKB2 Stop Delivery/Recall campaign – Replacing fastening nuts on the drive shafts on the rear axle

Overview

Incorrectly coated fastening nuts were used to secure the drive shaft and wheel hub on the rear axle of the affected vehicles.

As a result, the required tightening torque was not reached while fitting the components and there is no guarantee that the threaded joint between the drive shaft and wheel hub is secure enough.

To prevent the threaded joint from loosening, the fastening nuts on the drive shafts on the rear axle of the affected vehicles must be replaced and tightened to the required tightening torque.

| | |
|-------------------|------------------|
| Model type | 911 GT2 RS (991) |
| Model year | 2019 |
| Number | 1 |

Porsche Mobility

If requested, the mobility of the affected customer can be guaranteed by offering a suitable replacement vehicle.

Please invoice this additional service with the campaign scope via WWS.

Parts required

| Part No. | Designation | Quantity/vehicle | Parts return* |
|-----------------|------------------------|-------------------------|----------------------|
| WHT007021 | Hexagon nut, M22 x 1.5 | 2 | No |

Warranty processing

Please enter the campaign that was carried out in the Warranty and Maintenance booklet for the vehicle.

Scope 1:

- Vehicles **without** central wheel lock

| | |
|-------------|---------------|
| Damage code | AKB2 99 000 2 |
|-------------|---------------|

| | |
|--------------|-------|
| Working time | 77 TU |
|--------------|-------|

Scope 2:

- Vehicles **with** central wheel lock **(I-no. 478)**

| | |
|-------------|---------------|
| Damage code | AKB2 99 000 2 |
|-------------|---------------|

| | |
|--------------|--------|
| Working time | 101 TU |
|--------------|--------|

Further information

Work instruction

TI No. 77/19, Group 4, Service, AKB2

Vehicle list and allocation

[WWS Campaign Management](#)

Technical Information*

[PCSS / WWS Campaign Management](#)

* Please find enclosed the Technical Information in the form of a PDF file. Please bear in mind that this is provided for your information only. The version published in PCSS is the definitive version.

For further information, please contact:

Ryan Cooney

Regulatory Affairs

ryan.cooney@porsche.us

[AKB2 Replace Rear Axle Nuts Stop Sale Recall](#)

[Campaign.pdf](#)

221.9 KB

(57 views)

[AKB2 VIN List.xlsx](#)

8.1 KB

(97 views)

Created by [Ryan Cooney](#) on Aug 7, 2019 8:56 PM. Last modified by [Ryan Cooney](#) on Aug 9, 2019 9:09 PM.

Categories: 911 Carrera

Tags : [911](#), [recall campaign](#), [akb2](#)

907 Views

Content and Topics

Your Groups >

Your Content >

Your Places >

Personal

Edit Profile >

Change Password >

Manage

Admin Console >

PPN Administration >

Create

Discussion >

Files >

Document >

Collaboration >

Document

Blog Post >

Poll >

Message >

Event >

Photo Album >

Idea >

Space >

© 2019 Dr. Ing. h.c. F. Porsche AG. Legal notice. Copyright. Terms of use. Privacy Policy. Cookie Policy. [010](#)