



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

July 8, 2019

Mr. Mike Becker
Director of Corporate Compliance
Forest River, Inc.
2324 Century Drive
Goshen, IN 46528

NEF-150KL
19V-505

Subject: Improperly Installed Trailer Brake Controller

Dear Mr. Becker:

This letter serves to acknowledge Forest River, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

FOREST RIVER/ROCKPORT/2019

Mfr's Report Date: July 1, 2019

NHTSA Campaign Number: 19V-505

Components:

ELECTRICAL SYSTEM: INTEGRATED TRAILER BRAKE CONTROL
SERVICE BRAKES

Potential Number of Units Affected: 63

Problem Description:

Forest River, Inc. (Forest River) is recalling certain 2019 Rockport work trucks equipped with an optional trailer brake controller. The brake controller may have been wired improperly, which may prevent the brake controller from activating the trailer brakes when the vehicle's brakes are applied.

Consequence:

Without the trailer brakes assisting, stopping distances may be lengthened, increasing the risk of a crash.

Remedy:

Forest River will notify owners, and dealers will replace the brake controller, free of charge. The recall is expected to begin August 7, 2019. Owners may contact Forest River customer service at 1-574-327-2392. Forest River's number for this recall is 65-1046.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

NHTSA is missing critical, required information for this safety recall. This information must be supplied through the NHTSA Recalls Portal within 5 working days of confirming its accuracy:

- Your company's program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of your company's notification of owners, purchasers and dealers, in accordance with § 573.13 of this part. Your company's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by § 573.13 that is not in a general reimbursement plan shall be submitted in your company's report to NHTSA under this section. If your company submits one or more general reimbursement plans, your company shall update each plan every two years, in accordance with § 573.13. Your company's remedy program and reimbursement plans will be available for inspection by the public at NHTSA headquarters (49 CFR 573.6 (c)(8)(i)). If the vehicles are new and would be covered under the manufacturer's warranty program, please state that in the remedy section of your filing.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Kristin Lepper who may be reached by phone at 202-366-5227, or by email at kristin.lepper@dot.gov. We look forward to working with you.

Sincerely,



Joshua Neff
Acting Chief, Recall Management Division
Office of Defects Investigations
Enforcement