



Mercedes-Benz USA, LLC

Robert Veit
Managing Director
Vans USA

IMPORTANT SAFETY RECALL INTERIM NOTICE 2019070008

This notice applies to your vehicle

VIN: WD3PE7CC0 [REDACTED]

**Replace Rear-side Windows
NHTSA Recall #19V507**

August, 2019

WD3PE7CC0 [REDACTED]



- A safety defect exists in your vehicle.
- Remedy parts are not yet available for your vehicle.
- We will contact you again once parts are available.

Dear Valued Mercedes-Benz Sprinter Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Daimler AG (“DAG”), the manufacturer of Sprinter vans, has decided that a defect which relates to motor vehicle safety exists in certain Model Year 2018 - 2019 Mercedes-Benz Sprinter vehicles. Our records indicate that your vehicle is included in the affected population of vehicles.

DAG has determined that, due to a documentation error, certain Mercedes-Benz Sprinter vehicles (VS30; Platform 907) which should have been manufactured with rear side windows in laminated safety glass, were incorrectly manufactured with single-pane safety glass on single side windows in the rear on the right-hand side or on both sides. In the event of a side impact event or vehicle rollover, the fitted side windows may not fulfil the expected ejection mitigation function and occupants in the rear of the vehicle could be ejected. This could increase the risk of injuries, especially for passengers without seat belts.

We want to assure you that Daimler Vans USA is taking all necessary measures to remedy this situation for you. We are also working closely with the National Highway Traffic Safety Administration (“NHTSA”) and airbag suppliers to provide a remedy as soon as possible, and to prioritize repairs according to risk factors identified through testing. **Unfortunately, replacement parts are not yet available for your vehicle, and we will contact you again once parts become available.**

What should YOU do?



To enter your most recent contact information from your smartphone, scan the QR code to the left.

As soon as a suitable replacement part is available for your vehicle, we will send another letter notifying you to bring your vehicle to your local Authorized Mercedes-Benz Sprinter dealer to repair your vehicle free of charge.

In the meantime, please visit www.mbvans.com/sprinter/owners-resources/recall and enter your 17 digit VIN in the VIN Look-up tool, then enter your most recent contact information.

We also encourage you to sign up for recall alerts at www.nhtsa.gov/alerts.

Information for Owners

In the event that you are no longer the vehicle owner, or have had a change of address, please complete the reverse side and return the updated information in the enclosed envelope. If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 business days to comply with Federal Regulations.

We apologize for any inconvenience this situation may cause you.

Sincerely,

Mercedes-Benz USA, LLC

A Daimler Company
One Mercedes-Benz Drive
Sandy Springs, GA 30328
Phone (770) 705-0600

IMPORTANT

VIN: WD3PE7CC0 [REDACTED]

If for any reason YOU NO LONGER OWN THIS VEHICLE OR have a CHANGE OF ADDRESS, please COMPLETE THE SECTION BELOW, place in the ENCLOSED ENVELOPE, and DROP IN ANY MAIL BOX. If possible, provide the name and address of the present owner so that we may contact them.

EXPORTED

LEASE, VEHICLE RETURNED

SCRAPPED

SOLD

STOLEN

OTHER _____

NEW OWNER INFORMATION

MY NEW NAME OR ADDRESS IS:

[Grid for Last Name, First Name]

Last Name, First Name

[Grid for Street]

Street

Apt

[Grid for City, State, ZIP]

City

State

ZIP

[Grid for Email Address]

Email Address

[Grid for Phone (numbers only)]

Phone (numbers only)

[Grid for Mobile (numbers only)]

Mobile (numbers only)

Date

Signature