

August 12, 2019

Mr. Scott Goeb Product Safety Manager Pierce Manufacturing 2600 American Dr Appleton, WI 54912

Subject: Knee Air Bags Cushions may not Properly Inflate

Dear Mr. Goeb:

This letter serves to acknowledge Pierce Manufacturing's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

PIERCE/ARROW XT/2019 PIERCE/DASH/2019 PIERCE/ENFORCER/2019 PIERCE/IMPEL/2019 PIERCE/QUANTUM/2019 PIERCE/VELOCITY/2019

Mfr's Report Date: July 31, 2019

NHTSA Campaign Number: 19V-562

Components: AIR BAGS

Potential Number of Units Affected: 174

Problem Description:

Pierce Manufacturing (Pierce) is recalling certain 2019 Arrow XT, Dash, Enforcer, Impel, Quantum, and Velocity vehicles. Due to improper manufacturing, the passenger-side knee air bag (KAB) may not properly inflate during a deployment event.

Consequence:

In the event of a crash, if the KAB does not inflate properly, it may not provide the intended protection to the occupant, increasing the risk of injury.

Remedy:

Pierce will notify owners, and dealers will replace the KAB assembly, free of charge. The recall is expected to begin August 26, 2019. Owners may contact Pierce customer service at 1-888-974-3723.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-150MR 19V-562

NHTSA is missing critical, required information for this safety recall. This information must be supplied through the NHTSA Recalls Portal within 5 working days of confirming its accuracy:

- Your company's program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of your company's notification of owners, purchasers and dealers, in accordance with § 573.13 of this part. Your company's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by § 573.13 that is not in a general reimbursement plan shall be submitted in your company's report to NHTSA under this section. If your company submits one or more general reimbursement plans, your company shall update each plan every two years, in accordance with § 573.13. Your company's remedy program and reimbursement plans will be available for inspection by the public at NHTSA headquarters (49 CFR 573.6 (c)(8)(i)). If the vehicles are new and would be covered under the manufacturer's warranty program, please state that in the remedy section of your filing.

- Per the requirements of 49 USC 30119, please provide the part number, name and description of the component or components that need to be replaced to remedy this recall condition. This information should be provided in an amended 573 in the "Describe what distinguishes the remedy component from the recalled component" section.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at (202) 366-1060, or by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,

Joshua Neff Chief, Recall Management Division Office of Defects Investigations Enforcement

