

# Recall Quarterly Report

# 19V-584

**Manufacturer Name :** Mercedes-Benz USA, LLC.  
**NHTSA Recall No. / MFR Recall No. :** 19V-584 / 2019080006  
**Recall Subject :** Improperly Installed Pillar Covers  
**Owner Notification Beginning Date :** SEP 13, 2019  
**Owner Notification End Date:** SEP 13, 2019



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 4        | JUL 14, 2020    | 2020-2         | 1                 | 1              | 0                 | 0             |
| 3        | APR 18, 2020    | 2020-1         | 1                 | 1              | 0                 | 0             |
| 2        | JAN 13, 2020    | 2019-4         | 1                 | 1              | 0                 | 0             |
| 1        | OCT 07, 2019    | 2019-3         | 1                 | 0              | 0                 | 0             |

This Document Last Updated : JUL 17, 2020

## Definitions :

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.