



Reply Form

Jayco Corp Regulatory Compliance

903 South Main Street P.O. Box 460 Middlebury IN 46540

Publication: # 9901434 PRENOTIFICATION OF RECALL

Vin		Serial number	
Name:			
Address:			
City:		State:	Zip Code:
Home Phone #		Work Phone #	

Did your Inspection of the upper AND lower Steering Shaft Bolt find a White Line running from the bolt head to the nut, confirming that each was torqued to 45ft lbs. at the Jayco production facility?

- YES No repair is required on the top and/or the lower bolt/nut– ***Please return Reply Form***

- NO Repair is required. I verified that the locking feature is engaged (***at least two threads of the bolt are past the nut***) ***on the bolt/s*** that did not note the white line. This verification allows safe travel to a Dealer to have the bolt/s torqued to 45ft lbs. ***Please return Reply Form and contact a Dealer immediately for service appointment.***

Signature: _____ Date: _____

Please email this form to Compliance@jayco.com.
Thank you.