



New Safety Recall Advanced Communication – V95

FCA US LLC (FCA US) has announced a safety recall on certain 2020 Model Year (JT) Jeep® Gladiator vehicles.

REASON FOR THIS SAFETY RECALL

Some of the above vehicles may have a rear driveshaft that was manufactured without grease in the monoblock joint. This condition may cause the joint to overheat, seize and fracture. A fractured rear driveshaft could separate which may result in loss of motive power or possible road debris. Either condition can cause a vehicle crash without prior warning.

SERVICE ACTION

FCA US will conduct a voluntary safety recall to inspect the rear driveshaft monoblock joint and replace the rear driveshaft that may not have grease. Dealers will be notified of the launch of this safety recall by way of established communication methods. This recall is estimated to launch in 3rd Quarter of 2019.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries regarding involved vehicles.

Customer Services Field Operations
FCA US LLC