

Recall Quarterly Report**19V-659**

Manufacturer Name : Terex South Dakota, Inc.
NHTSA Recall No. / MFR Recall No. : 19V-659 /SN675
Recall Subject : Incorrect Holding Valve may Allow Boom to Drift
Owner Notification Beginning Date : OCT 25, 2019
Owner Notification End Date: OCT 25, 2019



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 1 | JAN 14, 2020 | 2019-4 | 42 | 12 | 0 | 0 |

This Document Last Updated : JAN 15, 2020

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).
Recall Population : The total number of products recalled by the manufacturer.
Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.
Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.
Total Removed : Products that have been scrapped, stolen, or exported.