## **Recall Quarterly Report**

**19V-664** 

Manufacturer Name : Subaru of America, Inc. NHTSA Recall No. / MFR Recall No. : 19V-664 /WUL-97 Recall Subject : Loose or Missing Brake Pedal Mounting Bracket Bolt Owner Notification Beginning Date : OCT 01, 2019 Owner Notification End Date: OCT 01, 2019



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JAN 21, 2020	2019-4	3,467	3,448	0	0

This Document Last Updated : JAN 22, 2020

## **Definitions :**

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.