

**Recall Quarterly Report****19V-681****Manufacturer Name :** Lucon, Inc.**NHTSA Recall No. / MFR Recall No. :** 19V-681 /**Recall Subject :** Insufficient Grease on Bearings may cause Failure**Owner Notification Beginning Date :** OCT 01, 2019**Owner Notification End Date:**

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	OCT 11, 2019	2019-4	8	8	0	0

This Document Last Updated : OCT 15, 2019

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.