

Wheel Nuts Safety Campaign

by [Eric Fauteux \(Eric_Fauteux\)](#) yesterday - last edited 3 hours ago

(91 Views)

Hey guys,

Thanks to your quality reports and to be patients regarding the current Ryker wheel nut situation. We have been able to understand the root cause & BRP has today released this safety warranty bulletin.

[ROADSTER 2020-1 Wheel Nut May Crack_137073](#)

The new nut 705402730 is now available, though it will be limited quantity for the coming weeks, we will be operating under a selective release system until we have enough parts available to ensure all dealers receiving a fair quantity of the wheel nuts, we will be putting priority for the first batch of wheel nut towards the southern states of the USA due to the fact that the first released units were shipped in these areas. Parts are already on his way to the international distribution center.

The new wheel nuts are designed with a new shape and look in order to define the difference between the new and previous nut * See below image.

The new wheel nuts are designed with a new shape and look in order to define the difference between the new and previous nut * See below image.



It is also important to know that the wheel nut tool and torque spec will be unchanged and that you will need to follow the shop manual and safety bulletin procedure along with this below is a quick video that can help with the procedure.

[2020-1 Wheel Nut May Crack_Help Video](#)

Eric