

Recall Quarterly Report**19V-686**

Manufacturer Name : Daimler Trucks North America LLC
NHTSA Recall No. / MFR Recall No. : 19V-686 /FL-828
Recall Subject : Insufficiently Tightened Flex Plate Fasteners
Owner Notification Beginning Date : NOV 19, 2019
Owner Notification End Date: NOV 19, 2019



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 3 | JUL 29, 2020 | 2020-2 | 618 | 467 | 0 | 1 |
| 2 | APR 28, 2020 | 2020-1 | 618 | 309 | 0 | 0 |
| 1 | JAN 28, 2020 | 2019-4 | 618 | 99 | 0 | 0 |

This Document Last Updated : JUL 29, 2020

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.