

IMPORTANT SAFETY RECALL INTERIM NOTICE

This notice applies to your vehicle

VIN: WD3PE7CC0 [REDACTED]

Abutting Wedge

NHTSA Recall #19V716

Daimler Vans USA, LLC

A Mercedes-Benz AG Company

Robert Veit

Managing Director

Vans USA

November, 2019

2019100010

WD3PE7CC0 [REDACTED]

[REDACTED]

- A safety defect exists in your vehicle.
- Remedy parts are not yet available for your vehicle.
- We will contact you again once parts are available.

Dear Valued Freightliner Sprinter Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Mercedes-Benz AG ("MBAG"), the manufacturer of Sprinter vans, has decided that a defect which relates to motor vehicle safety exists in certain Model Year 2019 Freightliner Sprinter vehicles. Our records indicate that your vehicle is included in the affected population of vehicles.

MBAG has determined that on certain Sprinter VS30 vehicles (platform 907), the wedge-type stop on the B-pillar (abutting wedge) on the driver & front passenger side may not have been installed as intended. The abutting wedge may have been mounted on holes that were drilled too large and/or incorrectly rotated. If a vehicle has an incorrectly installed abutting wedge and is involved in a severe frontal collision, the front doors could compress into the B-pillar. If this were to occur, significantly greater forces may be required to open the doors, which could make it difficult to exit the vehicle or lead to delay in accessing the vehicle from the outside.

We want to assure you that MBAG is taking all necessary measures to remedy this situation for you. We are also working closely with the National Highway Traffic Safety Administration ("NHTSA") and suppliers to provide a remedy as soon as possible.

Unfortunately, replacement parts are not yet available for your vehicle, and we will contact you again once parts become available. As soon as a suitable replacement part is available for your vehicle, we will send another letter notifying you to bring your vehicle to your local Authorized Freightliner Sprinter dealer to repair your vehicle free of charge.

As soon as a suitable replacement part is available for your vehicle, we will send another letter notifying you to bring your vehicle to your local authorized Freightliner Sprinter dealer to repair your vehicle free of charge. In the meantime, please visit www.freightlinersprinterusa.com/freightliner/owners-resources/recall and enter your 17 digit VIN in the VIN Look-up tool, then enter your most recent contact information.

We also encourage you to sign up for recall alerts at www.nhtsa.gov/alerts.

In the event that you are no longer the vehicle owner, or have had a change of address, please complete the reverse side and return the updated information in the enclosed envelope. If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 business days to comply with Federal Regulations.

We apologize for any inconvenience this situation may cause you.

Sincerely,



Daimler Vans USA, LLC
One Mercedes-Benz Drive
Sandy Springs, GA 30328
Phone (770) 705-0600

IMPORTANT

VIN: WD3PE7CC0 [REDACTED]

If for any reason YOU NO LONGER OWN THIS VEHICLE OR have a CHANGE OF ADDRESS, please COMPLETE THE SECTION BELOW, place in the ENCLOSED ENVELOPE, and DROP IN ANY MAIL BOX. If possible, provide the name and address of the present owner so that we may contact them.

- EXPORTED
- LEASE, VEHICLE RETURNED
- SCRAPPED
- SOLD
- STOLEN
- OTHER _____

NEW OWNER INFORMATION

MY NEW NAME OR ADDRESS IS:

[Grid for Last Name, First Name]

Last Name, First Name

[Grid for Street]

Street

Apt

[Grid for City, State, ZIP]

City

State

ZIP

[Grid for Email Address]

Email Address

[Grid for Phone (numbers only)]

Phone (numbers only)

[Grid for Mobile (numbers only)]

Mobile (numbers only)

Date

Signature