

U.S. Department of Transportation

National Highway Traffic Safety Administration

November 12, 2019

Mr. Mike Becker Director of Corporate Compliance Forest River, Inc. 2324 Century Drive Goshen, IN 46528 NEF-150KL 19V-754

1200 New Jersey Avenue SE Washington, DC 20590

Subject: Cooktop LP Gas Line May Melt and Cause Fire

Dear Mr. Becker:

This letter serves to acknowledge Forest River, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

FOREST RIVER/EVO/2020 FOREST RIVER/SALEM/2020 FOREST RIVER/WILDWOOD/2020

Mfr's Report Date: October 23, 2019

NHTSA Campaign Number: 19V-754

Components: EQUIPMENT

Potential Number of Units Affected: 41

Problem Description:

Forest River, Inc. (Forest River) is recalling certain 2020 EVO, Salem and Wildwood travel trailers. The trailer cooktops were installed with a rubber liquid propane (LP) gas line instead of a copper one.

Consequence:

The rubber hose may melt, allowing gas to enter the vehicle, increasing the risk of a fire.

Remedy:

Forest River has notified owners, and dealers will replace the rubber LP gas line with a copper gas line, free of charge. The recall began November 7, 2019. Owners may contact Forest River customer service at 1-909-873-3777. Forest River's number for this recall is 67A-1107.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



If the incorrect rubber LP hose has a part number, please update your filing to include (1) The name of the component or components, (2) A description of the component or components, and (3) The part number of the component or components. (49 USC 30119 (g)).

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Kristin Lepper who may be reached by phone at 202-366-5227, or by email at kristin.lepper@dot.gov. We look forward to working with you.

Sincerely,

Joshua Neff

Chief, Recall Management Division Office of Defects Investigations

Enforcement

