

Part 573 Safety Recall Report

19V-764

Manufacturer Name : Custom Fire Apparatus, Inc.

Submission Date : OCT 24, 2019

NHTSA Recall No. : 19V-764

Manufacturer Recall No. : 19V674



Manufacturer Information :

Manufacturer Name : Custom Fire Apparatus, Inc.

Address : 509 68th Ave

Osceola WI 54020

Company phone : 294-2555

Population :

Number of potentially involved : 57

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2002-2019 CustomFIRE Pumpers Rescues Tankers

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Received a list from Spartan of affected vehicles we purchased

Production Dates : JAN 01, 2002 - OCT 24, 2019

VIN Range 1 : Begin : 4S7AU2F935C049935 **End :** 4S7CT2D94KC086891 Not sequential

Description of Defect :

Description of the Defect : Service air reservoir system may not be pressure protected where the control line for the automatic tire chain system is connected.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the control line were to become severed, the service reservoir system may suddenly lose air. Although there would be a visual and audible warning indicating the loss of air, a sudden loss of the air brake system could increase the risk of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Spartan
Address : 1541 Reynolds Rd
Charlotte MICHIGAN 48813
Country : United States

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR
How Remedy Component Differs from Recalled Component : NR
Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Spartan to contact all end users
Planned Dealer Notification Date : NR - NR
Planned Owner Notification Date : NR - NR

* NR - Not Reported