

Attn: Indian Motorcycle Dealers

Subject: Safety Bulletin I-20-03 UPDATE

Key Actions & Timing: Please Read

Questions: Contact Indian Motorcycle Technical Service

Dear Indian Motorcycle Dealer,

A new version of Digital Wrench has been released, dated **4/24/20**. This version must be installed before the VCM reflash procedure in bulletin I-20-03.

Thank you for your attention.

Sincerely,

Indian Motorcycle Service