

November 1, 2019

Version 1

Safety Recall: Body Welds Missing**AFFECTED VEHICLES**

Year	Model	Trim	VIN Range
2019	Passport	ALL	Check the iN VIN status for eligibility. (only 1 vehicle is affected)
2019-20	Pilot	ALL	Check the iN VIN status for eligibility. (only 9 vehicles are affected)

A very limited number of 2019 Passport and 2019-20 Pilot vehicles potentially were manufactured with missing body welds. If a vehicle with missing welds is involved in a crash, the body may not function as designed to protect the occupants, leading to an increased potential for injury or death.

If you do an iN VIN status inquiry, and this bulletin appears as an open campaign, contact your DPSM for assistance. **Do not return the vehicle to the customer until it has been inspected by American Honda.**

END

CUSTOMER INFORMATION:The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.