



**IMPORTANT SAFETY RECALL**

This INTERIM notice applies to your vehicle, [REDACTED]  
Front Door Wiring Harness  
NHTSA Recall #19V820

Mercedes-Benz USA, LLC

Christian Treiber  
Vice President  
Customer Services

January, 2020

[REDACTED]  
[REDACTED]  
[REDACTED]  
[REDACTED]



Dear Mercedes-Benz Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Mercedes-Benz AG (“MBAG”), the manufacturer of Mercedes-Benz vehicles, has decided that a defect which relates to motor vehicle safety exists in certain Model Year (“MY”) 2019 G-Class vehicles. Our records indicate that your vehicle is included in the affected population of vehicles.

**What is the Concern?**

MBAG has determined that on certain MY 19 G-Class (463 platform) vehicles, the front door wiring harnesses might not be routed according to current production specifications. If the front door wiring harness is not routed according to specification, the opening and closing of the front doors might lead to individual wires becoming damaged. Damage to certain wires could impact the performance of certain safety features such as the side impact restraint system, the automatic unlocking of the door in the event of a crash, or the vehicle location in the event of an emergency call. Impact to any of these features could increase the risk of injury in the event of a crash.

**To remedy this issue, an authorized Mercedes-Benz dealer will modify the routing of the front door wiring harness or replace the wiring harness if necessary. Unfortunately, the parts to remedy this are currently not yet available.**

**We are working to obtain the necessary parts to correct this condition as quickly as possible. As parts become available, we will send you another letter asking you to take your vehicle to an authorized Mercedes-Benz dealer to have the recall completed free of charge.**

Should you have any concerns or questions regarding your vehicle before you receive the next recall letter when parts are available, please contact an authorized Mercedes-Benz dealer. If for any reason a dealer is unable to remedy your situation, we are always happy to hear from you. Please contact us at 1-800-367-6372. A new vehicle identification number (VIN)-based recall lookup tool, on our MBUSA.com website, now offers a search function that will indicate whether a vehicle has been subject to a safety recall, and whether that vehicle has had the free remedy performed. Please visit [www.MBUSA.com/recall](http://www.MBUSA.com/recall).

If you are no longer the vehicle owner, or have a change of address, please complete the reverse side of this letter and return the complete letter in the enclosed envelope. If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 days to comply with federal regulations.

If a Mercedes-Benz dealer for any reason is unable to remedy the situation without charge, or within a reasonable amount of time, pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153); or go to <http://www.safercar.gov>.

We regret any inconvenience this situation may cause you.

Sincerely,

Mercedes-Benz USA, LLC  
A Mercedes-Benz AG Company  
One Mercedes-Benz Drive  
Sandy Springs, GA 30328  
Phone (770) 705-0600

