News Channel Update |

Vehicle Compliance & Analysis

TO: Mercedes-Benz Dealer Principals, General Managers,	FROM: Gregory Gunther, Department Manager, Vehicle	
Sales Managers, Service Managers, Parts Managers	Compliance and Analysis, Engineering Services	
RE: Recall Campaign Initial Notification		
Soldering of Steering Control Unit	DATE: November 22, 2019	
MY19 253 (GLC-Class)		

IMPORTANT RECALL CAMPAIGN INFORMATION

Please see the attached documents related to the campaign listed above.

Please note that all customer inquiries should be directed to the Customer Assistance Center at 1-800-FOR-MERCEDES.

Sincerely,

Gregory Gunther

Department Manager, Vehicle Compliance & Analysis



News Channel Update |

Vehicle Compliance & Analysis

Campaign No.:	NHTSA ID	Campaign Desc.:	Soldering of Steering Control Unit			
TBA	19V822	PEND WELD SCU	Soldering of Steering Control Unit			
This is to notify you of a new Recall Campaign regarding the soldered contacts between the control unit and the electric motor of the power steering in 3 Model Year ("MY") 19 GLC-Class (253 platform) vehicles. The recall campaign will be visible on the www.safercar.gov website and may generate questions from customers. Affected VINs will be flagged in VMI as "PENDING" on November 22, 2019.						
Background						
Issue		Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year ("MY") 2019 GLC-Class vehicles (253 platform), the soldered contacts between the control unit and the electric motor of the power steering might not meet current production specification. If the contact pins are not soldered according to current production specifications, the control unit and the electric motor could lose complete electrical connection, resulting in the loss of the electric power steering assist, and increasing the risk of a crash.				
What We're Doing		MBUSA will conduct a voluntary recall. An authorized Mercedes-Benz dealer will replace the electric power steering control unit on the affected vehicles.				
Parts	A remedy is not yet available. An additional notification will be sent once a remedy is available.		ole. An additional notification will be sent once a remedy is			
Vehicles Affected						
Vehicle Model Year(s)		2019				
Vehicle Model		GLC-Class				
		Vehicle Popu	ilations			
Total Recall Population		3				
Total Vehicles in Deale		0				
Given this notice, it is a violation of Federal law for a dealer to sell or lease any new MY19 GLC-Class vehicles in dealer inventory covered by this notification until the vehicle has been repaired. Once the remedy is available, the vehicles will be flagged as "OPEN" and Work Instructions will be available in Star TekInfo. Once the repair is complete the vehicle may be sold or leased. Loaner and demonstrator vehicles may continue to be driven, but must not be retailed until repaired. Additionally, given this notice, it is a violation of Federal Law for car rental companies to rent MY19 GLC-Class vehicles covered by this notification until the vehicle has been repaired.						
Next Steps/Notes						
Customer Notification	Timeline	Customer letters will be m	nailed approximately one week after the remedy becomes available.			
AOMS/SOMS Rental Fleet Partners		AOMs – This recall may generate questions from your dealers. Please forward this notice to your dealers ASAP.				
		This recall may affect vehicles in your fleet. Please contact your respective MBUSA fleet representative for further information and next steps. For repairs, please contact your preferred MBUSA dealer.				
14/1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		1401104 1 1 1 1 1 1				

While we regret any inconvenience this may cause, MBUSA is determined to maintain a high level of vehicle quality and customer satisfaction. Please refer all customer inquiries to the Customer Assistance Center at 1-800-FOR-MERCEDES.

